





FHS1060

10'w x 5'h WL Hanging Sign	
Qty.	Part Number
4	WLM#035
2	WLM#003
2	WLM#010
1	WLM#062
1	BGO BAG-L

Notes:

- * Does not include Hanging Cables
- will fit inside CA600 or CA900 case





Step 1

After assembling the sign, locate the hanging points. There are openings on the zipper to allow for cables to be inserted



Step 2

Open the zippers to expose the hanging area, then wrap the cables around the vertical support pole



Step 3 Pull the cable through the opening in the fabric. Close the zippers.

*Hanging cables are not included in the kit, to be provided by on-site rigging team.