





FHS1560

15'w x 5'h WL Hanging Sign	
Qty.	Part Number
4	WLM#035
4	WLM#003
4	WLM#003
2	WLM#125
4	WLM#036-2-US
1	BGO-FABRIC-L bag

Notes:

- ^{*} Does not include Hanging Cables
- will fit inside CA600 or CA900 case





Step 1

After assembling the sign, locate the hanging points. There are openings on the zipper to allow for cables to be inserted



Step 2

Open the zippers to expose the hanging area, then wrap the cables around the vertical support pole



Step 3 Pull the cable through the opening in the fabric. Close the zippers.

*Hanging cables are not included in the kit, to be provided by on-site rigging team.