

18'w x 5'h WL Hanging Sign





SHS1860

18'w x 5'h WL Hanging Sign	
Qty.	Part Number
8	WLM#039L-US
12	WLM#003
8	WLM#004
16	WLM#125
16	WLM#036-2-US
2	BGO-FABRIC-XL bag

Notes:

- Does not include Hanging Cables
- Will fit inside a CA600 or CA900 case



Hanging Sign Rigging Instructions



Step 1After assembling the sign, locate the hanging points. There are openings on the zipper to allow for cables to be inserted



Step 2
Open the zippers to expose the hanging area, then wrap the cables around the vertical support pole



Step 3Pull the cable through the opening in the fabric.
Close the zippers.

^{*}Hanging cables are not included in the kit, to be provided by on-site rigging team.